

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3247	DATE	November 8,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>Since the support spring fixing the bulb in the front headlamp ground circuit is inappropriate, the contact pressure may become insufficient due to variability in the connector installation as well as the deterioration caused by the lighting heat over time resulting in spark and heat generation at the ground circuit contact point due to vibration etc. If use continues under this condition, the support spring could thermally deform and, in the worst case scenario, the front head lamp could not illuminate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-Z25A	「COLT」	2002~2004	53,088
UA-Z26A		2003	8,275
UA-Z27A		2002~2003	10,411
UA-Z28A		2003	2,425
		TOTAL	74,199