

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1981	DATE	Nov. 7, 2013
MANUFACTURER	DAIHATSU (PT. Astra Daihatsu Motor)		
DESCRIPTION OF DEFECT	Due to the unsuitable installation structure of acceleration pedal stopper, driver side floor mat possibly looses when getting in or out of the car or operating the acceleration pedal. With this condition, lower end of the acceleration pedal interferes with the stopper and repeating full acceleration pedal operation may makes a hole in the floor mat. In the worst case, the acceleration pedal may be caught in the hole and accordingly the engine revolution could not be lowered.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-S402M	TOWN ACE/LITE ACE	2008-2009	3,306
ABF-S402U			851
		TOTAL	4,157