

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	gai-1980	DATE	November 1, 2013
MANUFACTURER	Hyundai Motor Company (Japanese importer :Hyundai Motor Japan Co., Ltd )		
DESCRIPTION OF DEFECT	The stop lamp switch in the subject vehicles may experience intermittent switch point contact. This condition could potentially result in intermittent operation of the push-button start feature, illumination of the "ESC" (Electronic Stability Control) indicator lamp in the instrument cluster, intermittent interference with operation of the stop lamps.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GH-NF24	SONATA	2005~2006	465
GH-JM20	JM	2005~2007	99
GH-JM27		2005~2006	28
ABA-JM20		2009	2
ABA-JM27		2009	7
GH-GK27		Coupe	2006
ABA-GK27	2007~2008		51
ABA-TG27L	Grandeur	2007~2010	321
ABA-TG33		2006~2010	382
ABA-FD16	i30	2009~2010	718
ABA-FD20		2008~2009	34
ABA-FDW16	i30cw	2009~2010	27
ABA-FDW20		2009~2010	13
		TOTAL	2164