

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3285	DATE	DEC-27-2013
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Yoshiaki Nagao		
SUMMARY OF DEFECT	As for fuel injection pump of engine, some deliivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EDM-S601A	KIORITZ SPEED SPRAYER SSV601 F	2012	12
EDM-S1008A	KIORITZ SPEED SPRAYER SSV1008 F	2012	4
EDM-S672A	KIORITZ SPEED SPRAYER SSV672 F S	2012	6
		TOTAL	22