

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2003	DATE	Dec.26 th . 2013
MANUFACTURE	LOTUS CARS Plc (Japanese Importer :LCI Limited)		
DESCRIPTION OF DEFECT	As the length of rubber section at line feed hose of engine oil cooler on left side of vehicle rear was turned out to be improper, said rubber section itself could lead to be broken by conflicting with other functions around it under the resonance vibration with the motion of engine, by which engine oil would eventually become leaked in worst case. Once engine oil was leaked, not only it may come to hot engine components for resulting of fire, but it also calls for alarming of Oil Presser Tell Tale initially and damage itself eventually, if prolonged use of engine was made after oil leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LOTUS	EVORA S	2010~2011	20
		TOTAL	20