

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3284	DATE	December ,25 , 2013
MANUFACTURER	komatsu Ltd.		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some delivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-WA106AK	「WA30-6」	2011	30
EDM-WA107K	「WA40-6」,「WA50-6」	2011	2
EDM-WA107AK	「WA40-6」,「WA50-6」	2011	23
			TOTAL
			55