## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

## **Domestic** Import Vehicles

			7	
CAMPAIGN No.	3281	DATE	Dec 25, 2013	
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.			
DESCRIPTION OF DEFECT	In Transmission with clutch pack which does not install snap ring for fixing output shaft and ball bearing, the output shaft was pushed in when the transmission is carried in the vehicle, and parts inside clutch pack contact.  If it continues using in the state, abrasion powder is generated and lodge in hydraulic circuit, and transmission breaks down. In worst case, the vehicle cannot move.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-2GC	「MITSUBISHI MOTOR GRADER」	2013	14
EDR-4GD	「MITSUBISHI MOTOR GRADER」	2013	3
		TOTAL	17