

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3275	DATE	December 25.2013
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	Starter motor relay is located to the place where cooling air speed is high.It may allow drifting dust to come into the relay working in dusty environment.Continuous operation under this condition could form silicon oxide film at electric contact,which blocks electricity and makes starting engine impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-34L	「 EG326Y 」	2010	176
	「 EG328Y 」	2010	154
	「 EG330Y 」	2010	470
	「 EG334Y 」	2010	419
TOTAL			1219