

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2000	DATE	December 19 th , 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	One of the intake camshaft components might be faulty. This may lead to insufficient oil supply to the vacuum pump, which creates vacuum to be supplied to the brake booster. As a result, vacuum pump may become stuck because of insufficient lubrication, and vacuum may not be supplied to the brake booster. In the worst case, braking distance may be longer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3B20	BMW 320i	2012 - 2013	3,269
	BMW 320i Touring	2013	430
DBA-3X20	BMW 320i Gran Turismo	2013	158
DBA-3A20	BMW 328i	2011 - 2013	194
	BMW 328i Touring	2012 - 2013	149
DBA-3X28	BMW 328i Gran Turismo	2013	26
DBA-XG20	BMW 523i	2011 - 2013	655
DBA-XL20	BMW 523i Touring	2011 - 2013	174
DBA-XG28	BMW 528i	2011 - 2013	271
DBA-XL28	BMW 528i Touring	2011 - 2013	41
DBA-VL20	BMW X1 sDrive 20i	2012 - 2013	578
DBA-VM20	BMW X1 xDrive 20i	2011 - 2013	198
	BMW X1 xDrive 28i	2011 - 2013	597
DBA-WX20	BMW X3 xDrive 20i	2012 - 2013	477
	BMW X3 xDrive 28i	2012 - 2013	102
DBA-LL20	BMW Z4 sDrive 20i	2011 - 2013	146
TOTAL			7,465