

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1994	DATE	December 16 th 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to fitting of incorrect balance shaft module to the engine, noise or vibration may occur at an engine speed range from 5,000 rpm. When continue driving on that situation for longer time, it may cause crack on welding area or loosening of bolts on turbo charger etc.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-XL28	BMW 528i Touring	2013	1