

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 2 7 4	DATE	Dec.12.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate the electric circuit of the BCM (Body Control Module) that control the operation of the electric parts, the IC for the turn signal lamp may break by the electrical noise at the door lock operation. As a result, the turn signal lamp may have turned on. If the vehicle continues in this condition, in an extreme case, the IC may smolder due to heat up and this may lead to a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-SQ2F24	N I S S A N 「ATLAS」	2 0 1 3	7 8
CBF-SQ1F24			2 1
TKG-SZ2F24			8 6
SDG-SZ5F24			4 6
TKG-SZ1F24			3
SDG-SZ4F24			3
SKG-TZ2F24			2 3
SKG-TZ3F24			3
TKG-BSZ2F24	M I T S U B I S H I 「FUSO CANTER」		1 6
SDG-BSZ5F24			9
TKG-BSZ1F24			3
SDG-BSZ4F24			1
CBF-ASQ2F24	I S U Z U 「ELF」		3
TKG-ASZ2F24			2
SDG-ASZ5F24			1
		TOTAL	2 9 8