

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3298	DATE	Jan.29.2014
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the Continuously Variable Transmission (CVT) system of the subject vehicles, the nut which connects a shift control cable to the CVT could loosen due to improper tightening of the nut during vehicle assembly. If the vehicle is continuously operated in this condition, the nut could eventually fall off, and the shift control cable could separate from the CVT, causing a loss of shift control.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZGE20G DBA-ZGE20W	[WISH]	2013	553
DBA-ZGE25G DBA-ZGE25W		2013	163
		TOTAL	716