VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

Campaign No.	3295	Date	28, January, 2014			
Manufacturer	Kobelco Construction Machinery Co., Ltd.					
Description of	At the time of machine manufacture, tightening of the fixing clip on					
Defect	the hydraulic pump hose inserted to the suction pipe of the					
	hydraulic pump, which sends hydraulic oil to the hydraulic travel					
	motor and work devices, was improper. Because of this, the					
	tightening force of some clips has been insufficient. If the machine keeps being used with this condition, the hose may					
	come off and hydraulic oil may leak while the machine is being					
	operated and it may result in inability to travel due to shortage of					
	hydraulic oil.					

Туре	Commercial	Model year recalled		Number of
	Name			Vehicles
EDR-YE04	「SK125W」	2006 - 2013		248
			Total	248