

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3291	DATE	January 16 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		For the buses, it has been found that the leading edge of the bolts and nuts come out to the switchboard back, and interfere with the electrical wiring. Therefore, continuing to use as is, wire coating is worn, and in the worst case, there is a possibility that a short circuit occurs and lead to fire.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
U-LT232J	[CUBIC]	1990-1995	16	
P-LT312J		1990	7	
U-LT332J		1990-1995	91	
KC-LT333J		1995-1999	39	
P-LR212F	[JOURNEY K]	1990	2	
P-LR212J		1990	2	
U-LR232F		1991	4	
U-LR232J		1991-1995	22	
KC-LR233J		1995-1999	29	
P-LR312F		1990	2	
P-LR312J		1989-1990	49	
U-LR332J		1990-1995	87	
KC-LR333F		1997-1998	2	
KC-LR333J		1996-1999	143	
		TOTAL	495	