

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1998	DATE	January 16, 2014
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	<p>For 7 speed DSG gearbox control unit, due to improper gear oil, electrical short circuit occurs on the power supply circuit and related fuses get cut. If the defect happens during drive, clutch will be disengaged, which leads loss of driving motive; consequently vehicle slowly loses momentum till completely stops and no further driving possible.</p> <p>Nevertheless, under this condition, brakes, steering, and all other related driving functions are still available to maneuver the vehicle toward safety stop.</p> <p>If the defect happens during stationary period, engine cannot be started or still no further driving possible even engine can be started.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3CCDAC	「VW CC 1.8T」	2013	50
DBA-3CCAX	「VW Passat Sedan 1.4T」	2013	293
	「VW Passat Variant 1.4T」	2013~2014	1,117
ABA-6RCTH	「VW Polo GTI 1.4/132kw」	2013	151
DBA-6RCBZ	「VW Polo 1.2/77kw」	2013	4,932
DBA-6RCBZW	「VW Cross Polo 1.2/77kw」	2013	223
DBA-6RCPT	「VW Polo Blue GT」	2014	1
DBA-13CTH	「VW Scirocco 1.4/118kw」	2013	159
DBA-16CBZ	「VW The Beetle 1.2/77kw」	2013	5,129
DBA-16CBZK	「VW The Beetle cab 1.2」	2013	617
DBA-1KCBZ	「VW Golf 1.2/77kw」	2013	238
	「VW Golf Variant 1.2/77kw」	2013	581
DBA-1KCTH	「VW Golf 1.4/118kw」	2013	2
	「VW Golf Variant 1.4/118kw」	2013	360
DBA-1KCTHK	「VW Golf cab 1.4/118kw」	2013	28
DBA-1TCTH	「VW Touran 1.4/103kw」	2013	1,273
DBA-1TCTHW	「VW Cross Touran 1.4/103kw」	2013	344
DBA-AUCJZ	「VW Golf 1.2/77kw」	2013	91
DBA-AUCPT	「VW Golf 1.4/103kw」	2013	1,185
		Total	16,774