

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1997	DATE	January 16, 2014
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper fuse coating material, poor contact by nonconductive material (Zinc oxide) may cause partial exterior lighting failures including main head light, front fog light, positioning light, license plate light, tail light, rear fog light, brake light, additional brake light, reverse light, and turn signal light.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-5NCAW	「VW Tiguan 2.0T」	MY2009 – MY2010	5,096
ABA-5NCCZ	「VW Tiguan 2.0T」	MY2011	1,769
		Total	6,865