

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3288	DATE	January 15 ,2014
MANUFACTURER	ISUZU BODY CORPORATION		
DESCRIPTION OF DEFECT	When driving a vehicle in which the battery has been relocated, note that the crimped terminals of the battery harness are not fully water-resistant and will be corroded by water that enters from roads and via leaks through the slits of the corrugated tubing. The ongoing corrosion will eventually break the harness, and in extreme cases, the engine will fail to start and lamps will not go on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYJ77A	"GIGA"	2010-2012	65
LKG-CYJ77AA		2010-2012	26
LKG-CYJ77A "kai"(modified)		2011	3
LKG-CYL77AM		2011-2012	4
LKG-CYZ77AM		2012	1
PDG-CYJ52W8A		2008	1
PDG-CYJ77W8		2007-2010	11
PDG-CYJ77W8A		2010	3
PKG-CYJ77W8A		2009	4
QKG-CVR77A		2012	1
QKG-CYJ77A		2012-2013	32
QKG-CYJ77AA		2012-2013	11
QKG-CYJ77AZ		2012	2
QKG-CYL77AM		2012-2013	7
QKG-CYJ77A "kai"(modified)		2012	1
		TOTAL	172