

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3286	DATE	15-Jan-2014
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO.,LTD.		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some delivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
L2DA	「V2-3B」	2012	2
EDM-V36	「V3-6」	2011	21
EDM-RW05	「LK40Z-5」	2011	4
EDM-RX05	「LK50Z-5」	2012	3
		Total	30