

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	3314	DATE	Feb. 28, 2014
MANUFACTURER	KOBELCO CRANES CO.,LTD		
DESCRIPTION OF DEFECT	<p>Because shape of the oil pressure pipeline and its arrangement are inappropriate, in the power transmission device in a driving mood, hydraulic oil may leak from a cracked portion of the pipes by receiving a continuous stress due to the oil pressure pulsation. Therefore, the oil pressure in hydraulic pipes will be lost when continuously being used under this condition.</p> <p>In the worst case, a crack propagates and might not be able to drive because of not being able to transmit the power with the hydraulic oil.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-EE04	RK250-8	2013-2014	29
TOTAL			29