

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3310	DATE	February 20 ,2014
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In some trucks where excessive torque was used to tighten a band to fix a fuel tank, excessive force may be imposed on the spot-welding areas of the baffle plate (which prevents oscillation of the fuel fluid surface) in the tank. While a truck under this condition runs and vibrates from running on a road, the welding area may crack, causing, in the worst case, a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-NKR81AN PB-NKR81AR PB-NKR81N PB-NKR81R VD-NKR81AN	[ELF]	2005-2006	8,900
PB-NKS81AN PB-NKS81AR PB-NKS81N		2005-2006	312
PA-NPR81DR PA-NPR81N PA-NPR81R PB-NPR81AN PB-NPR81AR VD-NPR81AN		2005-2006	18,551
PB-NPS81AN PB-NPS81AR PB-NPS81N		2005-2006	607
PB-AKR81AN PB-AKR81AR PB-AKR81N PB-AKR81R	[ATLAS]	2005-2006	769
PB-AKS81AN PB-AKS81AR PB-AKS81N		2005-2006	38
PA-APR81DR PA-APR81N PA-APR81R PB-APR81AN PB-APR81AR		2005-2006	1,307
PB-APS81AN PB-APS81AR PB-APS81N		2005-2006	45
PB-BKR81AN PB-BKR81AR PB-BKR81N PB-BKR81R	[CONDOR]	2005-2006	190
PB-BKS81AR PB-BKS81N		2005-2006	13

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PA-BPR81N PA-BPR81R PB-BPR81AN PB-BPR81AR	[CONDOR]	2005-2006	301	
PB-BPS81AN PB-BPS81AR PB-BPS81N		2005-2006	16	
PB-LKR81AN PB-LKR81AR PB-LKR81N PB-LKR81R		2005-2006	655	
PB-LKS81AN PB-LKS81AR PB-LKS81N	[TITAN]	2005-2006	22	
PA-LPR81DR PA-LPR81N PA-LPR81R PB-LPR81AN PB-LPR81AR		2005-2006	1,666	
PB-LPS81AN PB-LPS81AR		2005-2006	34	
		TOTAL	33,426	