

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2009	DATE	February 20 th , 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>Due to the inappropriate design of the bulb carrier on the rear combination light, the connection might become loose by vehicle vibration. If lighting the lamps on under such circumstance, the temperature on the connector might increase.</p> <p>If the temperature increases repeatedly over a lengthy period, the connector parts will melt and conduction becomes poor, and as a result, one or more rear combination lights (tail, rear fog, brake, reverse, turn signal) will lose functionality with the warning lamp lighting on.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-NU25	BMW 525i	2007 - 2009	6,117
ABA-NU30	BMW 530i	2007 - 2009	2,257
ABA-NW40	BMW 540i	2007 - 2009	232
ABA-NW48	BMW 550i	2007 - 2009	249
ABA-NB50	BMW M5	2007 - 2009	305
		TOTAL	9,160