

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3306	DATE	February 14, 2014
MANUFACTURER	NITTSU SHOJI CO., LTD. 1-14-22 Kaigan, Minato-ku, Tokyo 105-8338 Japan		
DESCRIPTION OF DEFECT	The groove formed at the surface of the brake-plate were modified when redesigning the shape of the brake-shoe for avoiding the collision of the brake-shoe and the brake-plate. However, crack will occur when tension and compression concentrates at the groove. In the worst case, brake will not work.		
IMPROVEMENT MEASURE	Replace to a proper brake-plate for all vehicles.		
DISCREPANCE REPORTED	1	ACCIDENTS REPORTED	None
DISCOVERED REASON	Founded during 1 year car inspection.		
METHOD FOR NOTIFYING USERS AND SERVICE STATIONS	<ul style="list-style-type: none"> • Users: Direct mail or visit directly • Service Stations: Not necessary since all users are specified • Paste decal stated "No. 3306" near the chassis number for the vehicles completed. 		

TYPE	COMMERCIAL NAME	CHASSIS NUMBER, MANUFACTURED DATE	NUMBER OF VEHICLE
NT25H009	-	66-0011-033 30-Sep-08	1
NT34F002	-	60-3341 30-Jan-09	1
NT26D004	-	60-3361 27-Jul-09	1
NT32D004	-	60-3366 25-Sep-09	1
NT34D009	-	60-3381 25-Mar-10	1
NT33D008	-	60-3387 31-Mar-10	1
NT24H005	-	66-0694-0501 2-Mar-11	1
NT25H029	-	66-0778-0501~66-0779-0502 20-May-11	2
NT29K010	-	60-3439 25-Apr-12	1
NT30F004	-	60-3472 21-Mar-13	1
NT33D011	-	60-3491 20-Sep-13	1
NT35F010	-	60-3477 28-Sep-13	1
TOTAL 12 TYPES		TOTAL	13