

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3305	DATE	February 14,2014
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the fuel tank of the affected vehicles, since the temperature control at the filler pipe welding process was inappropriate, the welding strength in the filler pipe may have been insufficient. If use continues under this condition, the subject welding portion would be detached resulting in fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-A05A	「MIRAGE」	2013	211
		TOTAL	211