

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 2 9 4	DATE	F e b . 0 4 . 2 0 1 4
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the headlight, due to restrictions in the allowable temperature of the connecting terminal area of the electric wire for a light bulb, the terminal interlocking force of the said electric wire may be reduced because of the heat generated in the terminal for the light bulb. Therefore, if it is used continuously, the headlight may flicker due to engine vibration, etc., and in the worst case scenario, a conduction failure may occur in the said terminal area causing the headlight not be lighted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RN24J	YZF-R1	2009~2013	1,595
JBK-SG20J	MAJESTY YP250	2012~2013	2,880
		TOTAL	4,475