

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3329	DATE	28 Mar 2014
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>Since the shape of the bracket, which holds the transmission cable for Forward-Reverse operation of a load roller, is not appropriate, the bracket or/and the bolt holding the bracket can break, resulting from stress caused by vibration. Once they are broken, they become unable to hold the transmission cable, and the transmission for Forward-Reverse operation becomes improper. In the worst case, the vehicle can unexpectedly starts or stops against an operator's intentions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「ZC35C」	2010—2012	167
—	「HW30VWH-3」	2010—2012	21
—	「ZC35T」	2010—2011	16
—	「HW30VSH-3」	2012	1
—	「ZC50C」	2010—2012	171
—	「HW41VWH-3」	2010—2012	26
—	「ZC50T」	2010—2011	7
TOTAL			409