

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3332	DATE	March, 26, 2014
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to insufficient tightening torque of M5 screws for the Breather Shield which is inside the Cylinder Head Cover of the engine for agricultural tractor, they may loose and fall off. There is a possibility that those screws may be nipped under the Valve Bridge, subsequently the engine may exhaust black smoke and noise, and the output may decrease.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-XMY	「M115A」	2008～2012	53
	「M125A」	2008～2012	30
	「M135A」	2008～2011	117
	「GR115A」	2008～2012	6
	「GR125A」	2009～2012	6
	「GR135A」	2008～2011	6
		TOTAL	218