

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2015	DATE	March 25 th 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the software data status for the engine control unit, the on-board diagnosis function for primary oxygen sensor is not set. Thus, even in case there is a defect on primary oxygen sensor, the warning lamp will not light.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3B20	「BMW 320i」	2012	3,544
DBA-3A20	「BMW 328i」	2011 - 2012	1,722
DBA-XG20	「BMW 523i」	2011 - 2012	1,052
DBA-XL20	「BMW523i Touring」	2011 - 2012	546
DBA-XG28	「BMW528i」	2011 - 2012	247
DBA-XL28	「BMW528i Touring」	2011 - 2012	59
DBA-VM20	「BMW X1 xDrive 20i」	2011 - 2012	1,126
DBA-LL20	「BMW Z4 Drive20i」	2011 - 2012	211
TOTAL			8,507