

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3328	DATE	March 20,2014
MANUFACTURER	HOWA MACHINERY,LTD.		
DESCRIPTION OF DEFECT	<p>Some of the vehicles shipped do not meet safety standards due to insufficient efforts to confirm compliance with safety standards when optional components are attached to the motor sweeper.</p> <p>① The mounting position of the brake lights is incorrect.</p> <p>② Some of the lamps installed as brake lights do not meet brake light standards.</p> <p>③ Some of the lamps installed as reversing lights do not meet reversing light standards.</p> <p>④ Some of the lamps installed do not meet the restrictions applicable to lamps, etc.</p> <p>⑤ Yellow rotary lights have been installed.</p> <p>⑥ The total width of the vehicle exceeds 1.7 m when a side brush (working device) is mounted. This is beyond the range of specifications for a small-sized special motor vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HF66A	HF66A	1986 ~ 1995	42
HF66A2		1995 ~ 2005	16
HF66A3		2005 ~ 2013	27
HF68H	HF68H	1993 ~ 2001	8
HF64AH	HF64AH	2010 ~ 2013	3
		TOTAL	96