

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3327	DATE	Mar.6 2014
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On heavy- or medium-duty regular-service buses, tightening of the bolts that secure the part connecting the door engine to the mid sliding door is improper, and the bolts may loosen and stick out. If the bus continues to be used in this condition, protruded bolts will interfere with the inner pillar, causing faulty operation of the sliding door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-MP37FK	「FUSO AERO STAR」	2014~2014	30
QKG-MP37FM		2014~2014	9
QKG-MP35FM		2014~2014	15
TKG-MK27FH	「「FUSO AERO MIDI」	2014~2014	4
		TOTAL	58