

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2022	DATE	April 18, 2014
MANUFACTURE	Automobiles PEUGEOT Automobiles CITROEN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	①Due to insufficient strength of diaphragm inside the brake master VAC, the diaphragm may be deformed over time. This then prevents the brake pedal from returning to its rest position and eventually causes unintentional braking application and the brake lamp remained lit on.  ②Due to inappropriate installation of electrical wiring harness for drivers' powered seat, there is a risk of damage on wiring protector over time. And this may in the worst case, cause a short-circuit inside the wiring harness or pyrotechnic side-airbag to deploy unnecessarily.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T875F02	PEUGEOT 5008	2012 - 2013	①435 ②149
ABA-W25F02	PEUGEOT 508	2012	①13
ABA-W2W5F02	PEUGEOT 508	2012	①76
ABA-T85F02	PEUGEOT 3008	2013	②6
ABA-B85F02	CITROEN DS5	2012 - 2013	①177
		TOTAL	①701 846 ②155