

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2018	DATE	April 18, 2014
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper production of fuel pump union nut on the fuel tank, specified production tolerance is not secured; as a result, union nut becomes loose by the internal pressure effect and fuel leaks finally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-6RCGG	「Polo 1.4/63kw」	MY2010	2,211
DBA-6RCBZ	「Polo 1.2/77kw」	MY2010-MY2012	31,906
DBA-6RCBZW	「Cross Polo 1.2/77kw」	MY2010-MY2012	2,589
		Total	36,706