

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2014	DATE	April 18, 2014
MANUFACTURE	Caterpillar Japan LTD		
DESCRIPTION OF DEFECT	Engine glow plug can fail and/or deformed due to internal short circuit. This failure can cause engine starting difficulty, abnormal noise, vibration, combustion gas leakage etc.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-PWR	924K	2013	1
WDR-SWL	938K	2013	2
UDS-FER	950K	2013	14
UDS-FLL	962K	2013	2
		TOTAL	19