VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3348	DATE	15 April 2014		
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO., LTD				
DELECT	The small clearance around the turbo lubricant oil return pipe connection to flange to the turbo might appear by tightening bolt(s) loose due to inappropriate pipe manufacturing.				
	Continuous use of this condition might cause oil leak from this portion, then oil drop on exhaust manifold and result in smoke generation.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
EDR-HS61	「ZW140」	2013		60
EDR-HS63	「ZW180」	2013		50
			TOTAL	110