

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 3 4 7	DATE	Apr15,2014
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>The small clearance around the turbo lubricant oil return pipe connection to flange to the turbo might appear by tightening bolt(s) loose due to inappropriate pipe manufacturing.</p> <p>Continuous use of this condition might cause oil leak from this portion, then oil drop on exhaust manifold and result in smoke generation.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-T006	TADANO 「GR-160N-2」	2013	4
JDS-T006	TADANO 「GR-160N-2」	2008	1
		TOTAL	5