VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3346	DATE	April 15, 2014	
MANUFACTURER	KCM Corporation			
	The small clearance around the turbo lubricant oil return pipe connection to flange to the turbo might appear by tightening bolt(s) loose due to inappropriate pipe manufacturing. Continuous use of this condition might cause oil leak from this portion, then oil drop on exhaust manifold and result in smoke generation.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-60C3	60ZV-2	2013	15
EDR-RA08	LK150Z-6	2013	2
EDR-5DC1	55DV-2	2013	3
JDS-70C5	70ZV-2	2011	1
JDS-6DC1	65DV-2	2013	6
		TOTAL	27