## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3345	DATE	April.15.2014		
MANUFACTURER	Niigata Transys co.ltd.				
	The small clearance around the turbo lubricant				
	oil return pipe connection to flange to the turbo				
DESCRIPTION	might appear by tightening bolt(s) loose due to				
OF	inappropriate pipe manufacturing.				
DEFECT	Continuous use of this condition might cause oil				
	leak from this portion, then oil drop on exhaust				
	manifold and result in smoke generation.				

TYPE	COMMERCIAL NAME	Yl	DDEL EAR ALLED	NUMBER OF VEHICLE
EDR - NR4A	NR142	2011/2012		32
			TOTAL	32