

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3341	DATE	Apr.10.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the bus with automatic transmission installed, the durability of the automatic transmission control unit against heat was found to be insufficient and thus a crack could occur in some cases, on the welding fixing the elements inside of the unit. If the vehicle was continuously used under such situation, the crack could get enlarged, the electrical conductivity could be lost, dysfunctions in shifting of gear could occur, and in the worst case scenario, the tire could get locked or the re-starting of the engine could become impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-KV234L2	[HINO Blue Ribbon II]	2009~2010	9
PDG-KV234L2KAI			
LKG-KV234L3		2011~2013	75
QDG-KV234L3			
QKG-KV234L3			
QKG-KV234L3KAI			
PDG-KV234N2		2009~2010	71
PDG-KV234N2KAI			
LDG-KV234N3		2010~2014	136
LKG-KV234N3			
LKG-KV234N3KAI			
QKG-KV234N3			
QKG-KV234N3KAI			
PDG-KV234Q2			
LKG-KV234Q3			
QKG-KV234Q3		2011~2013	27
QKG-KV234Q3KAI			
		TOTAL	322