VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3340	DATE	April 10 ,2014
MANUFACTURER	MANUFACTURER ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT		In the bus with automatic transmission install the automatic transmission control unit against be insufficient and thus a crack could occur in welding fixing the elements inside of the unit continuously used under such situation, the creal real arged, the electrical conductivity could be shifting of gear could occur, and in the worst tire could get locked or the re-starting of the elements impossible.	st heat was found to n some cases, on the . If the vehicle was rack could get lost, dysfunctions in case scenario, the

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
PDG-LV234L2	[ERGA]	2009-2010	103
LDG-LV234L3 LKG-LV234L3 QDG-LV234L3 OKG-LV234L3		2010-2014	249
PDG-LV234N2 PKG-LV234N2	1	2009-2010	14
LDG-LV234N3 LKG-LV234N3 QDG-LV234N3 QKG-LV234N3		2010-2013	107
LDG-LV234Q3 QDG-LV234Q3 QKG-LV234Q3		2011-2013	27
	•	TOTAL	500