

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3342	DATE	Apr.9.2014
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the spiral cable assembly located behind the steering wheel, due to the shape and the location of the guide for the cable, a certain wire in the cable which provides connectivity to the air bag module could contact a small point of the guide. If the vehicle is continuously operated in this condition, the wire could wear and, in the worst case, may become damaged, causing the air bag warning light to illuminate, resulting in the deactivation of the driver's air bag in the event of crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ACA31W	[RAV4]	2005-2010	27,301
DBA-ACA36W		2005-2010	20,471
DBA-ACA33W	[VANGUARD]	2007-2010	28,645
DBA-ACA38W		2008-2010	15,714
DBA-GSA33W		2007-2010	2,103
DBA-GRX120	[MARK X]	2004-2009	46,606
DBA-GRX125		2004-2009	5,838
		TOTAL	146,678