VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3339	DATE	April 9, 2014	
MANUFACTURER	Komatsu Ltd.			
DESCRIPTION OF DEFECT	The small clearance around the turbo lubricant oil return pipe connection to flange to the turbo might appear by tightening bolt(s) loose due to inappropriate pipe manufacturing. Continuous use of this condition might cause oil leak from this portion, then oil drop on exhaust manifold and result in smoke generation.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-WA105	「WA200-6」	2013	252
EDR-WA103	「WA270-6」	2011~2013	176
EDR-WA108	「WA320-6」	2013	140
JDS-WA095	「WA380-6」	2013	42
EDR-M246K	「FD100」	2013	1
	「FD115」	2013	1
	「FD120」	2013	4
EDR-M247K	「FD135」	2013	3
	「FD150E」	2013	3
	「FD160E」	2013	11
EDR-M270K	「FD200」	2013	5
JDS-M269K	「FD250」	2013	1
	•	TOTAL	639