

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3337	DATE	April 3 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		As the carburizing treatment of the side gears for the differential gear system in the truck was inadequate on the manufacturing process, a hardness has been lost among some side gears. Continued use could break some teeth of the side gears causing an abnormal noise, and at worst, could break all the teeth making the truck become unable to travel.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-NHR85A	[ELF]	2013	13
TDG-NPS85AN TDG-NPS85AR		2013	4
TKG-LHR85A	[TITAN]	2013	1
TOTAL			18