

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2030	DATE	May. 9 , 2014
MANUFACTURER	AUDI AG (Japanese Importer : Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Technical background; Due to manufacturing tolerances, the fuel line may become damaged in individual cases after a period of time on Audi RS6 vehicles manufactured within a specific period. In the worst case, this can cause leakage.</p> <p>Remedy; The fuel line must is replaced and an additional retainer is installed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-4GCRDS	RS6Avant	2014	1
		TOTAL	1