

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-2033	DATE	May 15, 2014
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation )		
DESCRIPTION OF DEFECT	Due to insufficient strength of the piston rod and 2-3 speed gear fork, there might be cracking occurred during usage. If the vehicle is kept used, shift fork or piston rod will be damaged and in the worst case, may cause unplanned stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unspecified	FH12	2003-2005	632
	FM12	2003-2005	140
	FH	2005-2011	183
	FM	2005-2006	16
PJ-F2TCA1 PK-F2TCA1 PJ-F2TCA1 KAI	FH	2005-2007	54
	FM	2005-2006	28
PJ-F3RTF1 PK-F3RTF1	FH	2005-2007	47
	FM	2005-2006	20
BKG-B2TCA1	FH	2007-2008	50
	FM	2007-2008	7
BKG-B2TDA1	FH	2008-2010	51
	FM	2008-2009	4
BKG-B2TEA1	FH	2007-2010	94
	FM	2008-2009	17
BDG-B3RTF1	FH	2007-2010	43
	FM	2008-2009	9
LKG-H2TDA1 QKG-H2TDA1	FH	2010-2011	77
	FH	2010-2011	34
LKG-M2TEA1	FM	2010	1
LDG-H3RTF1	FH	2010-2011	7
LDG-M3RTF1	FM	2010	2
-B2TCA1-	FH	2008	1
-B2TDA1-	FH	2010	8
-B2TEA1-	FH	2008-2010	11
	FM	2008	1
-H2TDA1-	FH	2011	1
		TOTAL	1,538