

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3357	DATE	May 15, 2014
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	As joint construction between the lateral rod and the axle housing is improper in the front suspension systems, fastening bolts of the joint may become loose and the steering wheel may vibrate. In the worst case, the bolt can drop off and the steering function might decrease, with continuously using it as it is.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-JB23W	JIMNY	From 2012 to 2013	28,950
ABA-JB43W			2,045
ABA-JM23W	AZ-OFFROAD	From 2012 to 2013	749
TOTAL			31,744