

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3358	DATE	May 22, 2014
MANUFACTURER	KIRYU INDUSTRY CO., LTD.		
DESCRIPTION OF DEFECT	On the brake device in the passenger seat of an driving instruction car, since the snap pin which prevents the penetration rod pin of a brake pedal device from coming off was unsuitable, The snap pin extremely rarely came off from the penetration rod pin. Under these circumstances, the penetration rod pin may come off and instruction break system may not operate properly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GD2	「IMPREZA」	2007~2014	3
DBA-GH2			14
DBA-GJ2			202
DBA-GJ 3			233
		TOTAL	452