

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3359	DATE	May 22 ,2014
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	The production process of ball bearings in the gear shift unit for transmission of the hybrid bus was inappropriate, and some of the ball bearings may break. Continued use could lead to faulty transmission, and, in the worst case, the gears would be stuck and the bus could not start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QQG-LV234L3	[ERGA]	2013	14
QQG-LV234N3		2013	8
		TOTAL	22