

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3360	DATE	May 22 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the steering system of the bus, the clearance between the drag link and the fixing bolt for tie rod arm is too small. if the steering is turned left to its end of travel, there is a danger that the drag link may come into contact with the tip of the said bolt.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SDG-LR290J1 SKG-LR290J1	[ERGA MIO]	2011-2014	792
		TOTAL	792