

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3361	DATE	May.22.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the steering system of the bus, the clearance between the drag link and the fixing bolt for tie rod arm is too small. if the steering is turned left to its end of travel, there is a danger that the drag link may come into contact with the tip of the said bolt.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-KR290J1	[HINO Rainbow II]	2011~2014	492
SDG-KR290J1KAI			
SKG-KR290J1			
SKG-KR290J1KAI			
		TOTAL	492