

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3362	DATE	May.22.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain medium duty trucks, due to the insufficient strength of a bracket with relay valves for rear brakes and wheel parking brakes, there are some a crack is generated into the bracket concerned by vibration. If the vehicle is operated under the condition continuously, the crack of the bracket progresses, the air tube linked to a relay valve is separated by the damage of the bracket, and brake air leaks. In the worst case, braking force declines, or wheel parking brakes to be functioned by the leakage of brake air resulting the vehicle unable to move.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FG8JCAA	[HINO Ranger]	2010~2013	48
LDG-FG8JMAA		2010~2013	46
LDG-FG8JPAA		2010~2013	68
LDG-FG8JPAAKAI			
LDG-FG8JUAA		2010~2013	19
LDG-FG8JWAA		2010~2013	28
LDG-FG8JWAAKAI			
LDG-GK8JUAA		2010~2013	85
LDG-GK8JUAAKAI			
LDG-GK8JWAA		2010~2013	217
LDG-GK8JWAAKAI			
		TOTAL	511