VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No.

Gai-2036

DATE

May. 27. 2014

MANUFACTURE

BMW

(Japanese Importer: BMW Group Japan Corp.)

DESCRIPTION OF

DEFECT

BMW Motorrad has ascertained that, on account of a production fault, the side-stand switches are not correctly sealed. In rare cases water penetrating inside the switch can cause the side-stand switch to malfunction. The possibility of this malfunction causing the engine to die while the vehicle is on the move cannot be precluded.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C600S	「BMW C600S」	2013	225
C650GT	「BMW C650GT」	2013	306
F700GS	「BMW F700GS」	2013	189
F800GT	「BMW F800GT」	2013	180
F800GS	「BMW F800GS」	2013	41
F800GS-A	「BMW F800GS-A」	2013	68
EBL-R12NA	「BMW R1200GS」	2013	63
EBL-R12JA	「BMW R1200R」	2013	194
		TOTAL	1,266